

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

R110  
ESE  
1/8-1/4  
0.209 mi.  
1105 ft.

**BUS GARAGE @BRIGHTON PROP  
624 SHEEPSHEAD BAY ROAD  
BROOKLYN, NY**

**NY LTANKS S101508989  
N/A**

**Site 1 of 5 in cluster R**

**Relative:  
Higher**

**LTANKS:**

**Actual:  
2 ft.**

Name: BUS GARAGE @BRIGHTON PROP  
Address: 624 SHEEPSHEAD BAY ROAD  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9313186 / 2006-01-12  
Facility ID: 9313186  
Site ID: 320843  
Spill Date: 1994-02-07  
Spill Cause: Tank Failure  
Spill Source: Commercial/Industrial  
Spill Class: C3  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: RDDECAND  
Referred To: Not reported  
Reported to Dept: 1994-02-07  
CID: Not reported  
Water Affected: Not reported  
Spill Notifier: Other  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: True  
Remediation Phase: 0  
Date Entered In Computer: 1994-02-08  
Spill Record Last Update: 2006-01-12  
Spiller Name: Not reported  
Spiller Company: BRIGHTON PROPERTIES INC.  
Spiller Address: MR. VASLON  
  
Spiller County: 001  
Spiller Contact: Not reported  
Spiller Phone: Not reported  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 258473  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was ROMMEL 2/17/94 @0913HRS, MILLER SPOKE WITH CALLER, T. FIORENTINE: A PHASE 1 AND GEOPROBE INVESTIGATION WAS COMPLETED AND SUBMITTED TO BERGER/LEVER AND OWNER, ALVIN OF BRIGHTON PROPERTIES; A RECOMMENDATION ACCOMPANIED SUBMITTALS; USTS ARE OUT OF SERVICE (3,000 GAL #2, 550 OR 1,000 GAL WASTE OIL, 2-550 GAL GASOLINE AND ANOTHER LIKELY UST BENEATH A PAD. 10/10/95: This is additional information about material spilled from the translation of the old spill file: B.Y.X. 4/12/04-Vought-Spill transferred from Miller to Rommel as per Rommel. 1/12/06-Decandia-spill closed. Per AI Gulum of Sil Mechanics, tanks were pulled and wells were installed. See 94-14716 for additional info."  
  
Remarks: "LAB. TEST SHOWS CONTAMINATOR SOIL - TA NOT REGISTERED."  
  
All Materials:  
Site ID: 320843  
Operable Unit ID: 991633  
Operable Unit: 01  
Material ID: 570135

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: -1.00  
Units: L  
Recovered: .00  
Oxygenate: Not reported

Name: BRIGHTON PROPERTIES, LLC  
Address: 624 SHEEPSHEAD BAY ROAD  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9414716 / 2001-02-22  
Facility ID: 9414716  
Site ID: 320844  
Spill Date: 1995-02-08  
Spill Cause: Tank Failure  
Spill Source: Institutional, Educational, Gov., Other  
Spill Class: B3  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: SIGONA  
Referred To: Not reported  
Reported to Dept: 1995-02-08  
CID: Not reported  
Water Affected: Not reported  
Spill Notifier: Other  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: False  
Remediation Phase: 0

Date Entered In Computer: 1995-02-09  
Spill Record Last Update: 2001-02-26  
Spiller Name: ALVIN BOSLWO, PRESIDENT  
Spiller Company: BRIGHTON PROPERTIES,LLC  
Spiller Address: P.O. BOX 264  
Spiller County: 001  
Spiller Contact: Not reported  
Spiller Phone: Not reported  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 258473  
DEC Memo: ""  
Remarks: "PULLING THE TANK FROM THAT LOCATION AND DISCOVERED THE LEAK. CALLER WOULD LIKE A REP. FROM DEC TO SCENE."

All Materials:  
Site ID: 320844  
Operable Unit ID: 1008235  
Operable Unit: 01  
Material ID: 373445  
Material Code: 0022  
Material Name: waste oil/used oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Oxygenate:	Not reported
Site ID:	320844
Operable Unit ID:	1008235
Operable Unit:	01
Material ID:	373444
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported